



2004

FALCON
2000EX

SN 018

2004 FALCON 2000EX

SN 018

Highlights

COLLINS PRO LINE 21

AVANCE LX5 5G WI-FI

ALWAYS HANGARED

NEW PAINT 2015

CERAMICALLY COATED 2023

REFURBISHED INTERIOR 2015
(PARTIAL 2022)

SYNTHETIC VISION

ADS-B OUT, ADS-C, CPDLC, LPV,
WAAS, FANS 1/A+

Airframe Time & Cycles

TOTAL TIME SINCE NEW	7,255.3 Hours
TOTAL LANDINGS SINCE NEW	4,485 Landings

Engines & APU

	ENGINE #1	ENGINE #2	APU
	<i>Engine #1 is a loaner engine covered by the ESP Gold program</i>		
MODEL	PW308C	PW308C	GTCP-150(F2M)
SERIAL NUMBER(S)	PCE-CF0803LNR	PCE-CF0054	P-342
TOTAL HOURS SINCE NEW	2,728.7	6,737.4	3,995
TOTAL CYCLES SINCE NEW	1,769	4,179	N/A
MAINTENANCE PROGRAM	ESP Gold	ESP Gold	MSP Gold

Hours and Cycles updated as of 05/26/2026

Avionics

Collins Pro Line 21	TCAS II Change 7.1
Synthetic Vision	ADS-B Out
ADS-C	CPDLC
LPV	WAAS
FANS 1/A +	Dual File Servers with Dual Charts
Provisioned for XM Weather	Upgraded 88 Parameter Digital Flight Data Recorder (DFDR)
Collins AHRS	Dual Laser Ref IV IRU's
Airshow	
Upgraded Multi-scan Weather Radar with Smart Scan and Threat Detection	

Connectivity

INTERNET	Gogo AVANCE LX5 5G
----------	--------------------

2004 FALCON 2000EX

SN 018

Exterior

LAST PAINTED DEC 2015

MATTERHORN WHITE

STRIPE COLORS:

SAPPHIRE BLUE

SILVER GREY

Location

ROCKY MOUNTAIN AIRPORT (KBJC)
BROOMFIELD, CO

Equipment

Original Audio International

LED Landing & Taxi Lights

Brake Heating System

ICE Detection System

Additional Features

Oven

Microwave

Coffee Maker

USB Ports at every passenger seat

Cabin LED Lighting

Dual USB ports in cockpit

Wing Tank MOD C/W-SBF2000EX-171R1

Cockpit Refurbished as part of Pro Line 21 Upgrade

Weight & Balance

AIRCRAFT EMPTY WEIGHT

24,416.3 lbs

REWEIGH DUE (Part 135 only)

Nov 3, 2028

Next Major Inspection

2C Inspection required by February 2028.

2004
FALCON
2000EX

SN 018

Interior Configuration

10-PASSENGER LAYOUT

CREW JUMP SEAT

FWD GALLEY

ZONE 1


FOUR (4) PLACE CLUB SEATING

ZONE 2

FOUR (4) PLACE CONFERENCE
/ DINING GROUP OPPOSITE
TWO (2) FACING CLUB SEATS

AFT LAV

Cabin Floorplan



Shared Drive

Click [here](#) for additional photos and maintenance reports.

2004 FALCON 2000EX

N104QT

SN 018



2004
FALCON
2000EX

SN 018



2004
FALCON
2000EX

SN 018



2004
FALCON
2000EX

SN 018



2004
FALCON
2000EX

SN 018



2004 FALCON 2000EX

SN 018




Connect with Our Team

VanAllen is a full-service business aviation consulting firm focused on providing strategic guidance to business aviation users. For over 30 years, we have provided our clients insight and actionable recommendations to support the selection, application, and improvement of their private aviation services. We partner with our clients to provide innovative solutions, maximum value, and sustained excellence.

To learn more about this aircraft or connect with our team, contact us today.

VanAllen

525 Clubhouse Dr., Suite 150
Peachtree City, GA 30269
info@vanallen.com
(770) 507-5001

-  [VanAllen.com](https://www.vanallen.com)
-  [Linkedin.com/company/the-vanallen-group/](https://www.linkedin.com/company/the-vanallen-group/)
-  [VanAllen YouTube Channel](#)

